

Bishop, Everett

From: Bishop, Everett
Sent: Thursday, April 07, 2016 11:26 AM
To: Ponak, Rich
Cc: El-Abdaoui, Fatima
Subject: RE: (b) (6) - Eastern Shore

Tracking:	Recipient	Read
	Ponak, Rich	Read: 4/7/2016 11:28 AM
	El-Abdaoui, Fatima	Read: 4/7/2016 11:57 AM

Rich –

I appreciate the update of (b) (6) condo. I've passed your information onto OC managers who were contacted by (b) (6) so they are aware of what you found during your site visit.

Thanks!

Everett Bishop
US EPA
Office of Compliance
(202) 564-7032
bishop.everett@epa.gov

From: Ponak, Rich
Sent: Thursday, April 07, 2016 10:06 AM
To: Bishop, Everett <Bishop.Everett@epa.gov>
Cc: El-Abdaoui, Fatima <El-Abdaoui.Fatima@epa.gov>
Subject: RE: (b) (6) - Eastern Shore

Everett,

During my inspection on March 30, 2016 I collected five samples. All samples were none detect. I have also requested the abatement project documents from the owner. The abatement contractor removed two sliding glass doors and a small amount of dry wall associated with each door. This work was done under containment. The front door and a window were replaced without the dry wall being disturbed. I believe this is a non-enforcement asbestos issue and is a civil issue between the owners and tenants.

Thanks, Rich

From: Bishop, Everett
Sent: Tuesday, April 05, 2016 3:46 PM
To: Ponak, Rich <Ponak.Rich@epa.gov>
Subject: (b) (6) - Eastern Shore

Rich –

Just following up on your site visit to the Wight Bay Condos. Were samples taken? What can you report?

Thanks.

Everett Bishop
US EPA
Office of Compliance
(202) 564-7032
bishop.everett@epa.gov